



GIN

2010-07-06

Safety Recommendation by Gin Gliders

We strongly advise you to not fly in the rain on the Boomerang GTO and Boomerang 7. These high performance gliders are very susceptible to deep stall in the rain. The development path of modern high performance paragliders (high aspect ratio, 3 lines, profile type and high camber profiles) bears no allowance for these kind of gliders to fly when wet. If you see a shower coming during a flight, even a light one, we strongly advise you to go to land immediately. If you do fly in the rain, and if you enter a stall, which generally happens when your enter lift, do as follows. Do not perform any actions with your brakes, do not steer the wing, push on the "A" risers. If this is not sufficient to recover the flight, push the speed bar and maintain the action.

GIN GLIDERS からの安全上のアドバイス

弊社は、Boomerang GTO と Boomerang 7 の雨天でのフライトをしないよう強く勧告します。これらの高性能グライダーは、雨の中でディープストールの影響を非常に受けやすいです。最新の高性能パラグライダー（高いアスペクト比、3ライン、プロフィールタイプ、高いキャンバー特性）の開発経緯において、翼が濡れた状態でのフライトを考慮に入れていません。フライト中、雨が降り出すのを確認したら、たとえ小雨でも素早くランディングをすることを強くお勧めします。雨天のフライトにおいてストールした場合（リフトに入った場合に一般的に起こりえます）、以下の通りにして下さい。

ブレーキを用いるアクションや、ウィングの操作を実行せず、Aライザーを前方へ押してください。これでフライトの回復が十分でない時は、スピードバーを押して、状態を維持してください。

アエロタクトコーポレーション

125-0031

東京都葛飾区西水元 6-22-15

TEL:03-3608-8626

FAX:03-3600-7371

<http://www.aerotact.co.jp>